INTERDEPARTMENTAL CORRESPONDENCE

TO: Distribution

FROM: Joyce Downs

DATE: November 18, 1996

SUBJECT: EDF CCB MINUTES

Attached are the EDF CCB minutes of. November 18, 1996 Any questions or revisions in reference to this report, please contact Joyce Downs at extension 0980.

The EDF CCB convened at 2:00 p.m. on Monday November 18, 1996. The meeting was chaired by Jeff Albert..

Attendees:

Chairman	Jeff Albert
Organization	**Representative**
REL B	Burch, Eric
EDS/FOS	Davis, Debra
HITS/M&O	Downs, Joyce
EDS/SMO	Dorsey, Ken
MSS-B	Feinstein, Ed
EDS/SMO	Gilson, A.J.
REL A	Gorsky, Rich
HTSC-M&O	Kimble, M.
SCDO	Milburn, R.
SCMO-SWCM	Morgan, Dave
HITS/SCDO	Privor, Harvey
SUBCONTRACTS	Pyle, Galen
HISC/M&O	Roach, Mike
REL B	Van Steenberg, Charleen
HITS/MRS	Wheeler, Les

11/18/96 EDF CCB Meeting Minutes

CCR No.	Originator	Org	Disp	Title
96-1260	PRIVOR, H.	SCDO	A	VOB/View Server Upgrade
96-1261	WILDER, L.	RELB	D	Install S-Designer on MAC workstation

Notes: Loretta to switch to PC; License issue;

| 96-1263 | SMITH, D. | FOS | C | Move FOS MSS Server "eagle" to 1105 and install KFTP on it and on "Huey" |

Notes: D. Smith to provide floor plan; HTSC to move

96-1264   CHAWLA, J.   RELA   D   Install PowerBuilder 5.0 Beta for testing on a Sun Solaris server

Notes: Les W. to handle

96-1265   MCCARTNEY   RELB   C   EDF RelB Testbed Upgrade - Provide Loaner 4GB HP Disk for MSS Server

Notes: HTSC install

96-1266   WYNNE, D   RELA   C   FORTRAN 90 compiler upgrade for cle4sgi workstation

Notes: HTSC upgrade

96-1269   DIAZ, L   RELB   C   Install iFOR/Is license manager software on RELBHPMS

Notes: Is product installed on Mini-DAAC and where? HTSC install;

96-1270   LEWIS, W   RELB   C   Equipment for DBMS Performance Benchmark using Sybase II and Informix Universal Server

Notes: Need to talk to Randy Miller; Equipment must be tracked; Vendor will move hardware;

96-1271-   DIAZ, L   RELB   C   Install Flex/lm license manager software on MSSI

Notes: HTSC install

96-1277   V. STEENBERGRELB   C   Phase 1 of HW re-assign from various sources for establishing Release B Mini- DAAC environment

Notes: Action item for Charleen - need additional CCR for hardware; Task Lead is Charleen V.; Jean S. of HTSC needs t/b involved;

96-1279   MCCARTNEY   RELB   A   EDF Mini-DAAC Upgrade - Transfer 2 HP J210 from RelA mini-DAAC to RelB Testbed

96-1280   MCCARTNEY   RELB   C   EDF RelB Teastbed Upgrade - Document RelA mini-DAAC/connectivity net configuration

Notes: Updated cable list and network drawing required

96-1281   CLARK, B   RELA   C   MSSFCSGI3 Hardware Deinstall

Notes: EDS to handle

96-1282   MINOR, C.   SERC   D   Request for HTSC support to install Networker 4.2 on et3ws2 a SUN Sparc

Notes: Does ETC have license;

96-1283   MCCARTNEY   RELB   C   Installation of Xrunner 4.01 and LoadRunner 4.0 on "Sim" in EDF

Notes: Can HTSC support schedule?

96-1284   FEINSTEIN, E.   RELB   D   Move the Tivoli TME server to mss1

96-1285   FEINSTEIN, E.   RELB   C   Install Netscape Commerce server on relbhpms

Notes: Contingent upon license; Install Enterprise Server;

96-1287   BROWN, D.   RELA   C   Request for sudo privilege for STMGT

developers
Notes: First attempt Shell Scripts

96-1289   JEW, W.   RELA   R   Request to run remedy server as root

96-1290   MILBURN, R   RELA   C   Release A Sun (Solaris) machines need
                                                        Motif static libraries for the building of EOSView
Notes: Install on Golden Baseline; Tokyo, Bigfoot, King Kong:
        HTSC install only on these three machines

 96-1292   PRIVOR, H   SCDO   C   VOB/VIEW Server and Neetwork
                                                        Upgrade/Reorganization
Notes: HTSC install

96-1294   PARHAM, R.   SMO   C   Memory and Software Upgrade for Mini-
                                                        DAAC FDDI Switch
Notes: Vendor to install

96-1304   BROOME, R.   FOS   C   Request for Sudo Privileges
 Notes: Carlton of HTSC to coordinate; Delete S. Firth's sudo privileges.

96-1309   V.STEENBERG RELB   C   Move S-Designer 4.2.0 software from one
                                                        PC to another PC

Notes: HTSC to install

96-1310   PETERS, B.   TBD   C   Install NFS patch on dpre2sgi
 Notes: Action Item for Byron Peters; When finished testing, he is to share implications with
environment;

96-1311   V. STEENBERGRELB   C   Phase II of Release B Mini-DAAC HW re-
                                                        assignment request
Notes: Contingent upon Rel B having access to Rel A mini-DAAC machines

        Dispositon
        A = Approved no comment
        C = Approved w/comment
        D = Deferred
        F = Recommended for approval - Forwarded to ECS CCB
        R = Disapproved
        W = Withdrawn